

# PYLOX LAZER

## DESCRIPTION

Nippon Paint Pylox Lazer Spray Paint is a quick-dry-high-performance and versatile spray paint that can be used for top coating interior / exterior wood, steel & iron, aluminum alloy, galvanized steel and other metal surfaces.

Widely used in the line of building & decoration, household and advertisement.

## FEATURES

- No CFCs.
- With excellent coverage and adhesion.
- Easy and quick spray and minimize loss
- Fast drying and providing bright, smooth, durable surfaces

## USES

- For top coating interior / exterior wood, steel & iron, aluminum alloy, galvanized steel and other metal surfaces.
- Widely used in the line of building & decoration, household and advertisement.

## APPLICATION DATA

1. Clean surface thoroughly, removing all dirt, grease, oil, wax, rust, moisture, etc. Cover adjacent areas to protect from spray mist. Use at room temperature.
2. Shake can vigorously for one minute before spraying and occasionally while in use to ensure color uniformity and prevent clogging.
3. Test spray in a small inconspicuous area of the previously painted surface.
4. Hold can 12 – 16 inches (30 – 40 cm) from surface to be sprayed. Press the spray button firmly with steady even strokes while moving can rapidly back and forth. The finger must not protrude over the front edge of the spray button.
5. 2 or 3 thin coats with intermittences of 10 minutes are better than one continuous heavy coat.
6. Should paint bubble or run, you are too close to the surface or spraying too heavy a coat.
7. After use, turn can upside down and depress valve button for several seconds to clear valve until only gas emerges so as to prevent clogging
8. Discard empty cans in trash pickup. Do not place in home garbage compactor or burn.

## MSDS

- CONTENTS ARE EXTREMELY INFLAMMABLE AND UNDER PRESSURE
- Keep away from heat open flame, spark, and any other sources of ignition.
- Use only under well-ventilated conditions.
- Wear gloves, respirators, goggles, protective gear.
- Avoid prolonged contacting with skin, breathing vapor or spray mist. In case of contacting with eyes, flush repeatedly with warm water and contact the physician.
- If swallowed contact the physician immediately.

- Store in a cool, dry place below 115<sup>0</sup>F (46<sup>0</sup>C), higher temperature may lead to explosion.
- Do not puncture or incinerate the can even when empty.